

GSO NDC Citation Abatement Inspection #1555050

Citation 2 Item 2 (a) A-12 Guarded
Guard Installed 11-28-2021




GSO NDC Citation Abatement Inspection #1555050

Citation 2 Item 2 (b) A 14 Guarded
Guard Installed 02-03-2022




GSO NDC Citation Abatement Inspection #1555050

Citation 2 Item 2 (b) A 18 Guarded
Guard extended 01-25-2022



GSO NDC Citation Abatement Inspection #1555050

Citation 2 Item 2 (b) A 25 Guarded
Guard Modified to Cover Hole at Bottom
October 2021



GSO NDC Citation Abatement Inspection #1555050

Citation 2 Item 2 (b) A 26 Guarded
Guard Extended 1-25-2022



Citation 2 Item 2 (c) H 42 Guarded
Guard installed at bottom 12-27-2021




Citation 2 Item 2 (d) E4 Guarded
Guard damaged and repaired
02-01-2022



GSO NDC Citation Abatement Inspection #1555050

Citation 2 Item 2 (d) A 10 Guarded
Guard extended 01-25-2022



Citation 2 Item 2 (d) A-12 (back side) Guarded
Guard Extended 1-25-2022



Citation 2 Item 2 (d) A 14 Guarded
Guard Installed 02-03-2022



GSO NDC Citation Abatement Inspection #1555050


Citation 2 Item 2 (d) A-20 Guarded
Guard Extended 01-25-2022



Citation 2 Item 2 (d) A 26 Guarded
Guard Extended 01-25-2022



Citation 2 Item 2 (d) G 4 Guarded
Guard Installed 01-28-2022



GSO NDC Citation Abatement Inspection #1555050

Citation 2 Item 2 (d) SP 02 Guarded
Damage Guard Repaired 02-01-2022



GSO NDC Citation Abatement Inspection #1555050

Citation 2 Item 2 (e) 4002 Guarded
Guard installed 12-14-2021



GSO NDC Citation Abatement Inspection #1555050

Citation 2 Item 2 (e) 4003 Guarded
Guards Installed 12-14-2021



GSO NDC Citation Abatement Inspection #1555050

Citation 2 Item 2 (e) H 44 Guarded
Guard Modified to Mount Securely
02-18-2022



Citation 2 Item 2 (e) DS1 Guarded
Small Hole Damage Repaired on Guard 03-15-2022

